

GENESIS GAS & OIL, LLC
CALAMITY RIDGE UNIT
14-15C-1N100
SWISE SEC. 14, T1N, R100W
UNIT #COC-67497X
FEE FED
API #15-103-10462-00
.RIO BLANCO, COLORADO.



Inspection Photos
Location Name: CRU 14-15C-IN100
Location ID: 316411
Inspection Date: September 24, 2024

Location sign,
unnecessary equipment.

Sep 24, 2024 11:49:04 AM
+40.0489N -108.5837W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: CRU 14-15C-IN100
Location ID: 316411
Inspection Date: September 24, 2024

Tank battery and separator.



Sep 24, 2024 11:44:32 AM
+40.0491N -108.5837W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 14-15C-IN100

Location ID: 316411

Inspection Date: September 24, 2024

Unnecessary tank on
location.

Sep 24, 2024 11:48:10 AM
+40 0485N -108.5840W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 14-15C-IN100

Location ID: 316411

Inspection Date: September 24, 2024

Unnecessary tank on
location.

Sep 24, 2024 11:49:11 AM
+40.0489N -108.5837W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: CRU 14-15C-IN100
Location ID: 316411
Inspection Date: September 24, 2024

Debris.

Sep 24, 2024 11:49:19 AM
+40.0490N -108.5838W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: CRU 14-15C-IN100
Location ID: 316411
Inspection Date: September 24, 2024

Wellhead.



Sep 24, 2024 11:47:04 AM
+40.0489N -108.5840W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 14-15C-IN100

Location ID: 316411

Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
wellhead.

Sep 24, 2024 11:47:23 AM
+40.0489N -108.5840W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: CRU 14-15C-IN100
Location ID: 316411
Inspection Date: September 24, 2024

Potentially impacted
material within the tank
battery secondary
containment structure.

Sep 24, 2024 11:44:56 AM
+40.0491N -108.5839W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 14-15C-IN100

Location ID: 316411

Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
separator.

Sep 24, 2024 11:46:12 AM
+40.0491N -108.5841W



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos
Location Name: CRU 14-15C-IN100
Location ID: 316411
Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
separator.

Sep 24, 2024 11:46:09 AM
#40.0491N -108.5841W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources