



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Meter house,
unnecessary equipment.

Sep 24, 2024 1:43:17 PM
+40.0826N -108.5998W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:43:27 PM
+40.0826N -108.5997W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:44:56 PM
+40.0827N -108.6002W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Tank battery.

Sep 24, 2024 1:43:41 PM
+40.0825N -108.5997W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Various size holes and tears in the liner of the tank battery secondary containment structure.

Sep 24, 2024 1:44:02 PM
+40.0826N -108.5999W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Pump jack.



Sep 24, 2024 1:44:18 PM
+40.0826N -108.6000W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the wellhead. Note the salt staining and lack of vegetation.

Sep 24, 2024 1:44:27 PM
+40.0826N -108.6000W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the wellhead. Note the salt staining and lack of vegetation.

Sep 24, 2024 1:44:20 PM
+40.0826N -108.6000W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Potentially impacted material. Note the salt staining and lack of vegetation.

Sep 24, 2024 1:44:21 PM
+40.0826N -108.6000W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the pump jack exhaust.

Sep 24, 2024 1:44:48 PM
+40.0827N -108.6002W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-33

Location ID: 316577

Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
pump jack exhaust.

Sep 24, 2024 1:44:41 PM
+40.0826N -108.6002W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources