



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Location sign,
unnecessary equipment,
trash and debris.

Sep 24, 2024 11:55:21 AM
+40.0461N -108.5753W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Unnecessary equipment,
trash and debris.

Sep 24, 2024 11:54:40 AM
+40.0461N -108.5755W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 11:56:23 AM
+40.0464N -108.5752W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Tank battery.

Sep 24, 2024 11:52:40 AM
+40.0462N -108.5759W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Various size holes and tears in the liner of the tank battery secondary containment structure.

Sep 24, 2024 11:52:58 AM
+40.0461N -108.5760W



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105.

Sep 24, 2024 11:56:25 AM
+40.0464N -108.5752W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Wellhead.

Sep 24, 2024 11:55:58 AM
+40.0463N -108.5754W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CRU 4401D A23 1N100

Location ID: 316453

Inspection Date: September 24, 2024

Pump jack.

Sep 24, 2024 11:55:25 AM
+40.0461N -108.5753W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources