



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561

Inspection Date: September 24, 2024

CALAMITY RIDGE 14-33 location. Note the multiple tank batteries on location.

Sep 24, 2024 12:07:40 PM
+40.0540N -108.5821W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: CALAMITY RIDGE 14-33
Location ID: 423561
Inspection Date: September 24, 2024

Westernmost tank
battery.

Sep 24, 2024 12:05:26 PM
+40.0540N -108.5827W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561

Inspection Date: September 24, 2024

Various size holes and tears in the liner of the westernmost tank battery secondary containment structure.

Sep 24, 2024 12:05:41 PM
+40.0539N -108.5828W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561

Inspection Date: September 24, 2024

Eastermost tank battery.

Sep 24, 2024 12:04:28 PM
+40.0541N -108.5825W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561

Inspection Date: September 24, 2024

Various size holes and tears in the liner of the easternmost tank battery secondary containment structure.

Sep 24, 2024 12:06:29 PM
+40.0541N -108.5827W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561

Inspection Date: September 24, 2024

Potentially impacted material within the easternmost tank battery secondary containment structure.

Sep 24, 2024 12:04:52 PM
+40.0541N -108.5826W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561

Inspection Date: September 24, 2024

Unnecessary equipment,
trash and debris.

Sep 24, 2024 12:04:42 PM
+40.0541N -108.5826W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561


Inspection Date: September 24, 2024

Pump jack.

Sep 24, 2024 12:06:53 PM
+40.0541N -108.5823W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: CALAMITY RIDGE 14-33

Location ID: 423561

Inspection Date: September 24, 2024

Wellhead.

Sep 24, 2024 12:07:03 PM
+40 0541N -108.5822W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources