

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135



Photo 1 – Location Overview – Weeds



Photo 2 – Gas Engine

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Wellhead – Weeds

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135



Photo 5 – Wellhead



Photo 6 – 24-Hour Emergency not current

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135



Photo 7 – Tank Battery



Photo 8 – ECD and Flare

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135



Photo 9 – Propane Tank – 1000 Gallon



Photo 10 – Gas Meter

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135



Photo 11 – Rupture Pin Valve leaking



Photo 12 – Stained Soil at Rupture Pin Valve

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135




Photo 13 – Gas Meter Calibration Card




Photo 14 – Gas Meter Calibration Card

Inspection Photos
Location Name: Siefkin 11-30H-7-61
Location ID: 424135



Photo 15 – Valves open downstream of Meter



Photo 16 – Tank Battery

