



Inspection Photos

Location Name: FLETCHER GULCH 3-11

Location ID: 316582

Inspection Date: September 24, 2024

Meter house.

Sep 24, 2024 12:29:24 PM  
+40.0897N -108.6095W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-11

Location ID: 316582

Inspection Date: September 24, 2024

Pump jack and wellhead.  
Potentially impacted  
material adjacent to the  
wellhead, note the lack of  
vegetation.

Sep 24, 2024 12:28:46 PM  
+40.0901N -108.6098W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: FLETCHER GULCH 3-11

Location ID: 316582

Inspection Date: September 24, 2024

Pump jack and wellhead.  
Potentially impacted  
material adjacent to the  
wellhead, note the lack of  
vegetation.

Sep 24, 2024 12:28:51 PM  
+40.0901N -108.6098W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: FLETCHER GULCH 3-11

Location ID: 316582

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the wellhead, note the lack of vegetation.

Sep 24, 2024 12:28:24 PM  
+40.0901N -108.6097W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-11

Location ID: 316582

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the wellhead, note the lack of vegetation.



Sep 24, 2024 12:28:38 PM  
+40.0901N -108.6098W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: FLETCHER GULCH 3-11

Location ID: 316582

Inspection Date: September 24, 2024

Potentially impacted  
material adjacent to the  
pump jack.

Sep 24, 2024 12:28:11 PM  
+40.0900N -108.6097W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: FLETCHER GULCH 3-11

Location ID: 316582

Inspection Date: September 24, 2024

Potentially impacted  
material adjacent to the  
pump jack exhaust.

Sep 24, 2024 12:28:00 PM  
+40.0899N -108.6097W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources