

Inspection Photos

October 8th, 2024

Operator: Beeman Oil and Gas Inc - 7125

Location ID: 306993

Inspection Document #: 714001324

La Plata County, CO

Township: SW4NW4 12 33N 12W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hubbs 2
Location ID: 306993



Photo 1. View of the well disturbance taken from the northern edge facing center.
Note: Well API # is incorrect and reflecting API for Hubbs #1 well.



API #: 067-09390



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hubbs 2
Location ID: 306993



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of weedy Russian Thistle and Kochia debris encroaching on equipment.

API #: 067-09390

Inspection Photos
Location Name: Hubbs 2
Location ID: 306993



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of Hubbs 1 and 2 associated tank battery. Note: Weedy Russian Thistle debris are encroaching on tank berm and affecting berm integrity.

API #: 067-09390