

Inspection Photos

October 8th, 2024

Operator: Beeman Oil and Gas INC - 7125

Location ID: 306934

Inspection Document #: 714001327

La Plata County, CO

Township: SWSW 12 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Barbara 2
Location ID: 306934

10/8/24
+37.112849,-108.108362
28° NE



Photo 1. View of the well pad taken from the access point facing center. Note: well sign is no longer standing on its own, sign was propped for photo.

Inspection Photos
Location Name: Barbara 2
Location ID: 306934



Inspection Photos
Location Name: Barbara 2
Location ID: 306934



Photo 3. Associated remote tank battery.



Inspection Photos
Location Name: Barbara 2
Location ID: 306934

10/8/24
+37.113103,-108.110004
341° N



Photo 4. View of weedy debris/vegetation encroaching/over taking tank berm which is affecting permeability.

Inspection Photos
Location Name: Barbara 2
Location ID: 306934



Photo 5. View of impacted surface material with the tank secondary containment/berm.