

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/29NENW

Location ID: 335692

Date: 10/8/2024



Oct 8, 2024 at 13:44:03

Location Entrance – Photo #04037



Oct 8, 2024 at 13:45:43

Wellheads – Photo #04039

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/29NENW

Location ID: 335692

Date: 10/8/2024



Wellheads – Photo #04043



Gas Meters/Gas Lift – Photo #04046

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/29NENW

Location ID: 335692

Date: 10/8/2024



Undesirable Plant Species/Weeds – Photo #04041



Undesirable Plant Species/Weeds – Photo #04042

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/29NENW

Location ID: 335692

Date: 10/8/2024



Undesirable Plant Species/Weeds – Photo #04044



Unprotected Soil Stockpile – Photo #04038