

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/31NWNW

Location ID: 335674

Date: 10/8/2024



Location Entrance – Photo #04066



Wellheads – Photo #04068

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/31NWNW

Location ID: 335674

Date: 10/8/2024



Gas Meters/Gas Lift – Photo #04070



Insufficient Erosion Control – Photo #04072