



Inspection Photos

Location Name: FLETCHER GULCH 4-24

Location ID: 316583

Inspection Date: September 24, 2024

Location sign, meter
house.

Sep 24, 2024 12:40:28 PM
+40.0872N -108.6150W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-24

Location ID: 316583

Inspection Date: September 24, 2024

Pump jack and wellhead.

Sep 24, 2024 12:40:51 PM
+40.0869N -108.6149W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-24

Location ID: 316583

Inspection Date: September 24, 2024

Wellhead. Potentially impacted material adjacent to the wellhead, note the lack of vegetation.

Sep 24, 2024 12:41:00 PM
+40.0868N -108.6149W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-24

Location ID: 316583

Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
pump jack.

Sep 24, 2024 12:41:37 PM
+40.0867N -108.6148W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-24

Location ID: 316583

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 12:41:08 PM
+40.0868N -108.6149W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources