

# Inspection Photos

API: 043-06157

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 10/9/2024

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the location. All unused areas of the location must be reclaimed.



## Inspection Photos



**Photo 2.** Facing back south at the location. The wellhead has been covered with material.



## Inspection Photos



**Photo 3.** Facing east at the northwest side of the location. The pipe risers and utility appear to have been removed. All unused areas of the location must be reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:334402 | Date: 10/9/2024