



Inspection Photos

Location Name: Fletcher Gulch 4-13

Location ID: 316581

Inspection Date: September 24, 2024

Location sign and meter house.

Sep 24, 2024 12:45:14 PM
+40.0904N -108.6189W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 4-13

Location ID: 316581

Inspection Date: September 24, 2024

Wellhead and pump jack.
Potentially impacted
material adjacent to the
wellhead and pump jack.
Note the lack of
vegetation and salt
staining.

Sep 24, 2024 12:45:32 PM
+40.0906N -108.6190W



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 4-13

Location ID: 316581

Inspection Date: September 24, 2024

Wellhead and pump jack.
Potentially impacted
material adjacent to the
wellhead and pump jack.
Note the lack of
vegetation and salt
staining.

Sep 24, 2024 12:46:45 PM
+40.0906N -108.6190W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 4-13

Location ID: 316581

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the wellhead and pump jack. Note the lack of vegetation and salt staining.

Sep 24, 2024 12:46:27 PM
+40 0907N -108 6191W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 4-13

Location ID: 316581

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the wellhead and pump jack. Note the lack of vegetation and salt staining.

Sep 24, 2024 12:45:46 PM
+40.0907N -108.6190W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 4-13

Location ID: 316581

Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
pump jack exhaust.

Sep 24, 2024 12:45:58 PM
+40.0908N -108.6191W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 4-13

Location ID: 316581

Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
pump jack exhaust.

Sep 24, 2024 12:46:06 PM

+40.0908N -108.6191W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources