

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#1 overview of pit  
as taken from main gate.



Sep 13, 2024 11:44:14 AM  
40.30760621186346N 107.68920734524727W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#2 overview of pit.  
Note: excavator in background. Crews were removing contaminated soil from inside pit and hauling to Milner Landfill.



Sep 13, 2024 11:44:27 AM  
40.3076689504087N 107.68920323811471W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#3 Looking across  
pit. Note discharge piping  
at back of pit.



Sep 13, 2024 11:44:36 AM  
40.307733616791666N 107.68921497277915W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#4 Looking across  
pit. Note discharge piping  
at back of pit.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Sep 13, 2024 11:45:01 AM  
40.307936668395996N 107.68929552286863W

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#5 Photo of pit,  
moisture and water  
present in pit.



Sep 13, 2024 11:45:23 AM  
40.30806692317128N 107.68941789865494W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#6 Photo taken from northern end of pit complex.

Sep 13, 2024 11:45:52 AM  
40.308021241799N 107.68968218006194W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#7 photo of pit,  
discharge piping to right  
of photo. Moisture and  
water present in pit.



Sep 13 2024 11:46:20 AM  
40.30793914105743N 107.68991796299815W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#8 Area of former discharge. Water was seeping from ground below pit, into gulch.

Sep 13, 2024 11:46:40 AM  
40.30789920128882N 107.6900573540479W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#9 Area of former discharge. Water was seeping from ground below pit, into gulch.

Sep 13, 2024 11:46:53 AM  
40.307876570150256N 107.69010328687727W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#10 Photo taken with discharge piping in foreground. Note: water present in pit.

Sep 13, 2024 11:47:01 AM  
40.307850167155266N 107.69012139178813W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#11 looking from pit to area of former discharge. Note: moisture seeping from ground into gulch.

Sep 13, 2024 11:47:17 AM  
40.3078338643536N 107.69018936902285W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#12 Pit photo. Note:  
water in pit.

Sep 13, 2024 11:48:00 AM  
40.307568912394345N 107.69024234265089W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Iles  
Location ID: 116587  
Remediation Project #: 28244  
Inspection Date: 9/13/2024

Photo#13 area where crews had removed soil from pit for disposal. Crews started removing soil on the south west side of pit.

Sep 13, 2024 11:48:28 AM  
40.30740668065846N 107.69006531685591W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources