



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#1 culvert at county road. Water was not flowing on the ground surface past the culvert.





Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#2 below the
culvert, oil observed on
dry stream bed.

Oct 3, 2024 12:08:59 PM
40.812603041529655N 107.69156232476234W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#3 below the
culvert, oil observed on
dry stream bed.

Oct 3, 2024 12:09:09 PM
40 3126317076385N 107.69151069223881W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#4 below the
culvert, oil observed on
dry stream bed.





Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#5 taken inside pit
complex looking west
across pit.

Oct 3, 2024 12:13:50 PM
40.307648750022054N 107.68921991810203W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#6 taken from
inside pit, looking mostly
west.

Oct 3, 2024 12:14:19 PM
40.30771668534726N 107.6894040685147W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#7 taken inside pit
looking northwest, Note:
discharge piping.

Oct 3, 2024 12:14:39 PM
40.30771735589951N 107.68947363831103W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#8 fuel storage
tank.

Oct 3, 2024 T2:15:46 PM
40.30737156048417N 107.68943306989968W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#9 equipment
inside pit complex.

Oct 3, 2024 12:15:59 PM
40.30737076420337N 107.68954186700284W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#10 equipment
inside pit complex.

Oct 3, 2024 12:16:06 PM
40.30738681554794N 107.68960749730468W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#11 gate on west side of pit complex. This area previously had the observed gap in fence.

Oct 3, 2024 12:16:25 PM
40.30740215443075N 107.68981570377946W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#12 dirt in foreground is inside pit, this is the area of recent excavation.

Oct 3, 2024 12:16:35 PM
40.30742306727916N 107.68986674956977W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#13 looking across
pit to the north. Note:
discharge piping

Oct 3, 2024 12:16:38 PM
40.30742072034627N 107.68986381590366W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#14 looking across
pit to the east

Oct 3, 2024 12:16:45 PM
40.307409362867475N, 107.68988041207194W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#15 area of former discharge, some water was seeping out of the hill, in the excavated slope at the discharge, less water seeping than previously observed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#16 water in pit,
looking south. Note:
discharge piping.

Oct 3, 2024 12:32:19 PM
40:30780113302171N 107:69018241204321W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#17 looking across
pit, looking southeast.
Note: discharge piping at
bottom right of photo.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#18 looking east
across pit at the area
where soil has been
removed.

Oct 3, 2024 12:34:14 PM
40.30757016967982N 107.69026807509363W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#19 Cement sump.
The observed spill is not
in this photo. The spill
was observed, off
camera, to the left of
pictured.



Oct 3, 2024 12:18:48 PM
40.30731389299035N 107.68908471800387W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources




Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#20 Observed spilled fluid. Note: Tire tracks in spill. The spill was being tracked down the lease road. The corner of cement sump in back of photo, is the northwest corner of cement sump. Gate in background is used regularly for Ranch activity.

Oct 3, 2024 12:59:13 PM
40.30756224878132N 107.6889312453568W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 10/3/2024

Photo#21 tracked fluid on
access road.

Oct 3, 2024 12:59:53 PM
40.30744469258934N 107.6889452431351W