



Inspection Photos
Location Name: FLETCHER GULCH 4-33
Location ID: 316574
Inspection Date: September 24, 2024

Location sign and meter shack.

Sep 24, 2024 12:49:46 PM
+40.0845N -108.6208W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-33

Location ID: 316574

Inspection Date: September 24, 2024

Wellhead and pump jack.
Potentially impacted
material adjacent to the
wellhead and pump jack.
Note the salt staining and
lack of vegetation.

Sep 24, 2024 12:50:14 PM
+40.0843N -108.6209W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-33

Location ID: 316574

Inspection Date: September 24, 2024

Wellhead and pump jack.
Potentially impacted
material adjacent to the
wellhead and pump jack.
Note the salt staining and
lack of vegetation.

Sep 24, 2024 12:50:22 PM
+40.0843N -108.6210W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 4-33
Location ID: 316574
Inspection Date: September 24, 2024

Wellhead and pump jack.
Potentially impacted
material adjacent to the
wellhead and pump jack.
Note the salt staining and
lack of vegetation.

Sep 24, 2024 12:50:28 PM
+40 0842N 108 6210W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 4-33
Location ID: 316574
Inspection Date: September 24, 2024

Trash.

Sep 24, 2024 12:49:51 PM
+40.0845N -108.6208W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-33

Location ID: 316574

Inspection Date: September 24, 2024

Trash.

Sep 24, 2024 12:50:00 PM
+40.0844N -108.6208W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources