

Inspection Photos

10/08/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424

Inspection Doc: 696206373

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 1: Operator appears to have performed grading operations to address tracking and stabilization concerns. Unclear if controls are adequate to address the tracking and stabilization concerns during wet conditions.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 3: Anchor markers do not comport with 603.j/1003.a requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources