

Interim Reclamation and Stormwater Inspection

September 10, 2024

Operator: FULCRUM ENERGY OPERATING # 10805

Location ID: 449274

Inspection Document #: 712300066

Jackson County, CO

Logan Maxwell
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Rabbit Ears 0681 23 Pad

Location ID: 449274



Photo 1. Photo taken from the entrance of Location, illustrating Operator's sign.



Photo 2. Photo taken the entrance of the Location, facing SW. Photo illustrates Operator re-contoured pad surface and edge of interim reclamation area.

Inspection Photos
Location Name: Rabbit Ears 0681 23 Pad
Location ID: 449274



Photo 3. Photo illustrates Operator re-contoured and seeded interim area. The seed mix is predominantly introduced species that are not reflective of reference area vegetation.



Photo 4. Photo taken from the edge of reclamation area, facing southwest. Photo illustrates the interim reclamation area.



Inspection Photos
Location Name: Rabbit Ears 0681 23 Pad
Location ID: 449274



Photo 5. Photo taken at southwestern working pad surface, facing south. Photo illustrates stormwater runoff outlet.



Photo 6. Photo taken at well head. Photo illustrates Operator signage.

