


Operator: HPR

Location Name: Anschutz Equus Farms 4-62-32 SESE

Loc ID: 451928

Inspection: 717700308





CA: Stained soil next to the well needs to be removed. Properly dispose of oily waste in accordance with 905.3

CA Resolution: Operator has reported that identified stained soil has been appropriately addressed to comply with the 900 series.