

Inspection Photos
Location Name: Eastern Hills 4-65 17-18 1EH
Location ID: 474845



Pic 1 wellheads



Pic 2 LACT

Inspection Photos
Location Name: Eastern Hills 4-65 17-18 1EH
Location ID: 474845



Pic 3 tanks



Pic 4 ECD, VRT, automation

Inspection Photos
Location Name: Eastern Hills 4-65 17-18 1EH
Location ID: 474845



Pic 5 Separators



Pic 6 Compressor