

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614



Photo # 4772 From entrance to location



Photo # 4773 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614




Photo # 4774 Location



Photo # 4775 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614



Photo # 4776 Location



Photo # 4777 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614



Photo # 4778 Location



Photo # 4779 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614



Photo # 4780 Burner exhaust stacks on separator units lack bird protection/wildlife hazard



Photo # 4781 Burner exhaust stacks on separator units lack bird protection/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614



Photo # 4782 Burner exhaust stacks on separator units lack bird protection/wildlife hazard



Photo # 4783 Open ended piping/available for entry by wildlife/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614



Photo # 4784 Production tank lacks required labeling



Photo # 4785 Production tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad

Location ID: 335614



Photo # 4786 Unmarked deadman



Photo # 4787 2nd Unmarked deadman