

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4512 From entrance to location




Photo # 4513 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4514 Location



Photo # 4515 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623




Photo # 4516 Location



Photo # 4517 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4518 Location




Photo # 4519 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4520 Location



Photo # 4521 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4522 Location



Photo # 4523 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4524 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 4525 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4526 Wellhead sign weathered & cracking/some required info is illegible



Photo # 4527 Wellhead sign weathered & cracking/starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623




Photo # 4528 Wellhead sign weathered & cracking/starting to become illegible



Photo # 4529 Wellhead sign weathered & cracking/starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Photo # 4530 Stored farm equipment on location & stored trailers & shed in the interim area.



Photo # 4531 Stored trailers & shed in the interim area.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Farris RWF 34-31 Pad

Location ID: 418623



Oct 10, 2024 at 9:51:13 AM
CO

Photo # 4532 Stored trailer & misc in the interim area



Oct 10, 2024 at 9:53:32 AM
CO

Photo # 4533 Stored truck, trailer & misc in the interim area