

# Inspection Photos

October 8th, 2024

Operator: Beeman Oil and Gas - 7125

Location ID: 306991

Inspection Document #: 714001344

La Plata County, CO

Township: SENE 14 33N 12W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Gladys 2  
Location ID: 306991



Photo 1. View of the well pad taken from the access road facing center.



API #: 067-09363

Inspection Photos  
Location Name: Gladys 2  
Location ID: 306991



**Photo 2.** Well pad disturbance is infested with flowering Russian Knapweed.