



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Location sign and meter shack.

Sep 24, 2024 1:16:41 PM
+40.0827N -108.6104W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Pump house and tank
battery.



Sep 24, 2024 1:12:30 PM
+40.0831N -108.6101W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the pump house.

Sep 24, 2024 1:12:35 PM
+40.0831N -108.6101W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Potentially impacted
material adjacent to the
pump house.

Sep 24, 2024 1:12:49 PM

+40.0831N -108.6100W



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Pump house and tank
battery secondary
containment structure.
Note the unnecessary
equipment.

Sep 24, 2024 1:13:04 PM
+40.0831N -108.6100W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the pump house and tank battery secondary containment structure.

Sep 24, 2024 1:13:18 PM
+40.0832N -108.6100W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Inspection Date: September 24, 2024

Unnecessary equipment
adjacent to the pump
house.

Sep 24, 2024 1:12:54 PM
+40.0831N -108.6100W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Potentially impacted material within the tank battery secondary containment structure. Note the salt staining adjacent to the access hatch.

Sep 24, 2024 1:13:08 PM
+40.0831N -108.6100W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Tank battery secondary
containment structure in
disrepair.

Sep 24, 2024 1:13:49 PM
+40.0832N -108.6100W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Potentially impacted material within the tank battery secondary containment structure. Note the salt staining and evidence of livestock with the tank battery secondary containment structure.

Sep 24, 2024 1:14:11 PM
+40.0832N -108.6100W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Various size holes and tears in the liner of the tank battery secondary containment structure. Note the evidence of livestock with the tank battery secondary containment structure.

Sep 24, 2024 1:14:39 PM
+40.0832N -108.6099W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Evidence of livestock with the tank battery secondary containment structure, note the TEP Rocky Mountain LLC signage on the tank.

Sep 24, 2024 1:13:53 PM
+40.0832N -108.6100W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

TEP Rocky Mountain LLC
signage on the tank.

Sep 24, 2024 1:14:59 PM
+40.0832N -108.6099W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:15:32 PM
+40.0830N -108.6101W



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:15:50 PM
+40.0828N -108.6102W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:16:05 PM
+40.0828N -108.6102W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:16:19 PM
+40.0827N -108.6103W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:16:22 PM
+40.0827N -108.6103W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:16:51 PM
+40.0828N -108.6104W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

Potentially impacted material adjacent to the wellheads, note the salt staining and lack of vegetation.

Sep 24, 2024 1:17:03 PM
+40.0829N -108.6103W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

API 05-103-10888,
potentially impacted
material adjacent to the
wellhead, note the salt
staining and lack of
vegetation.

Sep 24, 2024 1:17:09 PM
+40 0829N -108 6103W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Inspection Date: September 24, 2024

API 05-103-11095,
potentially impacted
material adjacent to the
wellhead, note the salt
staining and lack of
vegetation.

Sep 24, 2024 1:17:12 PM
+40.0829N -108.6103W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources