



Inspection Photos

Location Name: FLETCHER GULCH 4-44

Location ID: 316576

Inspection Date: September 24, 2024

Location sign and meter house.

Sep 24, 2024 1:20:14 PM
+40.0813N -108.6129W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-44

Location ID: 316576

Inspection Date: September 24, 2024

Meter house.

Sep 24, 2024 1:20:02 PM
+40.0807N -108.6130W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-44

Location ID: 316576

Inspection Date: September 24, 2024

Well head and pump
jack.

Sep 24, 2024 1:20:41 PM
+40.0812N -108.6132W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-44

Location ID: 316576

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:20:59 PM
+40.0812N -108.6133W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 4-44

Location ID: 316576

Inspection Date: September 24, 2024

Unnecessary equipment
and potentially impacted
material adjacent to the
pump jack.

Sep 24, 2024 1:21:06 PM
+40.0811N -108.6134W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources