

**Shawnee Oil Development Inc**  
**USA Shaw 19**  
**Location ID: 313419**



**Marked anchor**



**Wellhead sign illegible and incomplete**



**Shawnee Oil Development Inc**  
**USA Shaw 19**  
**Location ID: 313419**



**Unmarked anchor**



**Location of oil seep on downhill slope to creek drainage**



**Shawnee Oil Development Inc**  
**USA Shaw 19**  
**Location ID: 313419**



**Oil seep covered with soil**



**Soil removal to cover oil seep**



**Shawnee Oil Development Inc**  
**USA Shaw 19**  
**Location ID: 313419**



**Flowline leaks**




**Cellar open to wildlife**



Shawnee Oil Development Inc  
USA Shaw 19  
Location ID: 313419



Incomplete sign at tank battery



Incomplete tank labels



Shawnee Oil Development Inc  
USA Shaw 19  
Location ID: 313419



**Inadequate tank berm**



**Inadequate tank berm**



Shawnee Oil Development Inc  
USA Shaw 19  
Location ID: 313419



**Marked anchor?**



**Marked anchor?**



**Shawnee Oil Development Inc**  
**USA Shaw 19**  
**Location ID: 313419**



**Location from Southeast corner**



**Location from Southwest corner**



**Shawnee Oil Development Inc**  
**USA Shaw 19**  
**Location ID: 313419**



**Location from Northwest corner**



**Location from Northeast corner**