

## Inspection Photos

**Operator: AMERICAN HELIUM OPERATING LLC - 10841**

**Location Name: COCKLEBUR DRAW UNIT #1**

**Location ID: 311866**

**API #: 05-113-06051**

**Inspection Date: 10/10/2024**

**Inspection Doc#: 693807792**



**Wellhead with sign and fence**



**Separator and Meter housing with sign**



## Inspection Photos

**Operator: AMERICAN HELIUM OPERATING LLC - 10841**

**Location Name: COCKLEBUR DRAW UNIT #1**

**Location ID: 311866**

**API #: 05-113-06051**

**Inspection Date: 10/10/2024**

**Inspection Doc#: 693807792**



**Tank Battery**



**Risers for metering station (removed)**



## Inspection Photos

**Operator: AMERICAN HELIUM OPERATING LLC - 10841**

**Location Name: COCKLEBUR DRAW UNIT #1**

**Location ID: 311866**

**API #: 05-113-06051**

**Inspection Date: 10/10/2024**

**Inspection Doc#: 693807792**



**Blowdown tank for metering station**



**Risers for metering station (removed)**

**Unused tanks and shed cover.**