

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403957039

Date Received:
10/15/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
CAERUS ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302884
Inspection Date: 10/08/2024 FIR Submit Date: 10/09/2024 FIR Status:

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335641

Location Name: N PARACHUTE Number: WF01B-36A36A596 County:
Qtrqr: NENE Sec: 36 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.577975 Longitude: -108.108661

FACILITY - API Number: 05-045-00 Facility ID: 335641

Facility Name: N PARACHUTE Number: WF01B-36A36A596
Qtrqr: NENE Sec: 36 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.577975 Longitude: -108.108661

CORRECTIVE ACTIONS:

1 CA# 199501

Corrective Action: Secure equipment to comply with Rule 608.e. Date: 10/14/2024

Response: CA COMPLETED Date of Completion: 10/14/2024

Operator Comment: Closed pump house door to comply with rule 608.e. Also added labeling on separator per comment/recommendation of inspector.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: _____

Title: Compliance

Date: 10/15/2024 8:30:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403957045	Secured pump house door
403957047	Added glycol labeling to separator

Total Attach: 2 Files