

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #1 Tanks (weeds on, in and around berm, and throughout location).

Photo #2 Tanks (weeds on, in and around berm, and throughout location).

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #3 Tanks (weeds on, in and around berm, and throughout location).



Photo #4 Separators, meter run and ECDs (weeds around equipment and throughout location).

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #5 Separators, meter run and ECDs (weeds around equipment and throughout location).



Photo #6 Trash and weeds.

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #7 Trash and weeds throughout location.



Photo #8 Trash and weeds throughout location.

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #9 Pump jack (weeds throughout location).

Photo #10 Pump jack (weeds throughout location).