

Inspection Photos
Location Name: UPRR 23 PAN AM M2
Location ID: 319982



Photo #1 Tanks (weeds in and around berms and graffiti on tanks).



Photo #2 Tanks (weeds in and around berms and graffiti on tanks).

Inspection Photos
Location Name: UPRR 23 PAN AM M2
Location ID: 319982




Photo #3 Tanks (weeds in and around berms and graffiti on tanks).



Photo #4 Meter house and separator (weeds around separator).

Inspection Photos
Location Name: UPRR 23 PAN AM M2
Location ID: 319982



Oct 2, 2024 at 11:14:15 AM
Adams County Inspections

Photo #5 Well head (weeds around the well head).