

Inspection Photos
Location Name: UPRR 23 PAN AM D #3
Location ID: 319938



Photo #1 Tanks (weeds in, on and around berms).

Photo #2 Tanks (weeds in, on and around berms).

Inspection Photos
Location Name: UPRR 23 PAN AM D #3
Location ID: 319938



Photo #3 Meter run and separator (weeds throughout location).



Photo #4 Well head (weeds around well head).