



Inspection Photos

Location Name: FLETCHER GULCH 3-13

Location ID: 316578

Inspection Date: September 24, 2024

Location sign and meter house.

Sep 24, 2024 1:29:46 PM
+40 0882N -108.6024W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-13

Location ID: 316578

Inspection Date: September 24, 2024

Well head and pump
jack.

Sep 24, 2024 1:32:10 PM
+40.0883N -108.6023W



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-13

Location ID: 316578

Inspection Date: September 24, 2024

Well head.

Sep 24, 2024 1:30:18 PM
+40.0883N -108.6021W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-13

Location ID: 316578

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:31:42 PM
+40.0883N -108.6019W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-13

Location ID: 316578

Inspection Date: September 24, 2024

Unnecessary equipment.

Sep 24, 2024 1:31:33 PM
+40.0883N -108.6019W



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 3-13

Location ID: 316578

Inspection Date: September 24, 2024

Stockpiled material on location.

Sep 24, 2024 1:30:06 PM
+40.0882N -108.6022W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 3-13
Location ID: 316578
Inspection Date: September 24, 2024

Stockpiled material on location.

Sep 24, 2024 1:29:52 PM
+40.0882N -108.6024W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources