

Inspection Photos
Location Name: Annis #1
Location ID: 323195



Photo 1: Location from entrance



Photo 2: Wellhead

Inspection Photos
Location Name: Annis #1
Location ID: 323195




Photo 3: Tank Battery Sign



Photo 4: Tank Battery

Inspection Photos
Location Name: Annis #1
Location ID: 323195



Energy & Carbon Management Commission
40.12106, -104.60822, 1474.6m, 332°
Oct 14, 2024 11:58:28

Photo 5: BBLs not legible



Energy & Carbon Management Commission
40.12106, -104.60829, 1471.9m, 199°
Oct 14, 2024 11:59:02

Photo 6: Equipment

Inspection Photos
Location Name: Annis #1
Location ID: 323195



Inspection Photos
Location Name: Annis #1
Location ID: 323195



Inspection Photos
Location Name: Annis #1
Location ID: 323195

