

Antler Energy LLC  
Ptasynski 5  
Location ID: 312975




When replaced additional information will be required

Unlabeled tank

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**No sign at tank battery**



**Replace labels when faded and illegible**

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**Open end tank valve**



**Unmarked anchor**

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**1 of 2 production pits**



**1 of 2 production pits**

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**Unmarked anchor**



**Debris**

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**Well sign on the ground and missing required information**

**Unmarked anchor**

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**2 of 2 production pits**

**2 of 2 production pits**

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**Risers missing rain caps**



**Location from Southwest entrance**

**Antler Energy LLC  
Ptasynski 5  
Location ID: 312975**



**Location from Northwest corner**



**Location from Northeast corner**