

Inspection Photos

API: 009-06612

Operator: **CHOLLA PRODUCTION LLC**

Inspection Date: 10/14/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing east. The winter wheat crop appears to be uniformly re-established.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321049 | Date: 10/14/2024

Inspection Photos



Photo 2. Drone aerial photo facing east. The former tank battery site next to the two track road 600' east of the wellsite. There appears to be impacted soils from the associated tank battery.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321049 | Date: 10/14/2024

Inspection Photos



Photo 3. Facing down toward the associated facility location.. There are impacted soils that will need to be remediated.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321049 | Date: 10/14/2024