

# Inspection Photos

API: 009-06630

Operator: **CHOLLA PRODUCTION LLC**

Inspection Date: 10/14/2024

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south at the abandoned wellsite. There is no crop growth where the well was located approx. 60'x50'.





## Inspection Photos



**Photo 2.** Facing north at the abandoned wellsite. There is no crop growth where the well was located approx. 60'x50'.





## Inspection Photos



**Photo 3.** Facing west at the surrounding winter wheat crop off the location.

