

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWNE

Location ID: 334920

Date: 10/14/2024



Location Entrance – Photo #04177



Wellheads – Photo #04179

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWNE

Location ID: 334920

Date: 10/14/2024



Separators – Photo #04181



Tank Battery – Photo #04182

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWNE

Location ID: 334920

Date: 10/14/2024



**Lack of Stabilization – Photo #04178**



**Insufficient Tracking BMPs – Photo #04183**