

Inspection Photos

API: 009-06215

Operator: **SOVEREIGN OPERATING COMPANY LLC**

Inspection Date: 10/14/2024

County: BACA



Inspection Photos



Photo 1. Drone aerial photo facing northeast at the associated tank battery location adjacent to the County Road. The crop has not established at the former tank battery. There appears to be impacted soils that will need to be remediated.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321018 | Date: 10/14/2024

Inspection Photos



Photo 2. Drone aerial photo facing north. The crop has not established at the former wellsite. There appears to be impacted soils that will need to be remediated.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321018 | Date: 10/14/2024

Inspection Photos



Photo 3. Drone aerial photo facing south. The crop has not established at the former wellsite. There appears to be impacted soils that will need to be remediated.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321018 | Date: 10/14/2024