

Inspection Photos

API: 009-06175

Operator: **SOVEREIGN OPERATING COMPANY LLC**

Inspection Date: 10/14/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing north adjacent to the County Road. There is a pipe riser/pig launcher approximately 250' south of the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321009 | Date: 10/14/2024

Inspection Photos



Photo 2. Drone aerial photo facing north down to the former wellsite. There are areas where desirable perennial vegetation has not established.



Inspection Photos



Photo 3. Drone aerial photo facing south down to the former wellsite. There are areas where desirable perennial vegetation has not established.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321009 | Date: 10/14/2024