

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32
Location ID: 324118



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Nest Site & in close proximity to NSO Habitat area & Bald Eagle Roost Site. Location is approximately 207 yards from Cache Creek.

Section/Township/Range: 32 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32
Location ID: 324118



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32
Location ID: 324118



Photo # 6507 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill



Photo # 6508 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill