

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 10/15/2024



Location Entrance – Photo #04207



Wellheads – Photo #04211

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 10/15/2024



Oct 15, 2024 at 11:01:51
2917-3681 County Road 309
Parachute CO 81635
United States

Separators – Photo #04208



Oct 15, 2024 at 11:02:39

Tank Battery – Photo #04210

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 10/15/2024



Wellhead/Meter – Photo #04212



Weathered Wellhead Sign – Photo #04213

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 10/15/2024



Insufficient Erosion Control – Photo #04234



**Insufficient Erosion Control/Transport of Sediment from
Lease Road – Photo #04236**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 10/15/2024



**Insufficient Erosion Control/Transport of Sediment from
Lease Road – Photo #04237**



**Insufficient Erosion Control/Transport of Sediment from
Lease Road – Photo #04238**