

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FORSHEE-67S95W/3NWNE

Location ID: 334808

Date: 10/15/2024



Location Entrance – Photo #04215



Wellhead – Photo #04218



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FORSHEE-67S95W/3NWNE

Location ID: 334808

Date: 10/15/2024



Wellhead – Photo #04219



Separator – Photo #04217



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FORSHEE-67S95W/3NWNE

Location ID: 334808

Date: 10/15/2024



**Tank Battery – Photo #04216**



**Insufficient Erosion Control – Photo #04234**



Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FORSHEE-67S95W/3NWNE

Location ID: 334808

Date: 10/15/2024



**Insufficient Erosion Control/Transport of Sediment from  
Lease Road – Photo #04236**



**Insufficient Erosion Control/Transport of Sediment from  
Lease Road – Photo #04237**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FORSHEE-67S95W/3NWNE

Location ID: 334808

Date: 10/15/2024



**Insufficient Erosion Control/Transport of Sediment from  
Lease Road – Photo #04238**