

Inspection Photos

October 15th, 2024

Operator: BMG Drilling Corporation - 7650

Location ID: 428734

Inspection Document #: 714001350

La Plata County, CO

Township: SENE 4 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Jacques 2
Location ID: 428734

10/15/24
301° NW



Photo 1. View of the project area from the southern edge facing center.

Inspection Photos
Location Name: Jacques 2
Location ID: 428734



Photo 2. View of the northeast corner of the disturbance. Vegetation establishment is minimal in this area compared to other reclaimed portion. Remnant gravel also observed.

Inspection Photos
Location Name: Jacques 2
Location ID: 428734

10/15/24
288° W



Photo 3. View of the western portion of the disturbance where vegetation establishment appears more successful. Germinating vegetation includes but is not limited to Sand Dropseed, Blue Grama and James Galleta.

Inspection Photos
Location Name: Jacques 2
Location ID: 428734



Photo 4. View of rill erosion and sediment transportation observed in the location fill and cut slopes, additional stabilization/stormwater BMPs needed in these areas.

Inspection Photos
Location Name: Jacques 2
Location ID: 428734

10/15/24
275° W



Inspection Photos
Location Name: Jacques 2
Location ID: 428734

10/15/24
358° N



Inspection Photos
Location Name: Jacques 2
Location ID: 428734

10/15/24
292° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area composed of Sagebrush, Rubber Rabbitbrush and Smooth Brome.

API #: 067-06292