

Inspection Photos

October 15th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326337

Inspection Document #: 714001351

La Plata County, CO

Township: SESE 1 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Simmons A1
Location ID: 326337

10/15/24
189° S



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos
Location Name: Simmons A1
Location ID: 326337



Photo 2. View of Musk thistle observed in various patches throughout the disturbance.

Inspection Photos
Location Name: Simmons A1
Location ID: 326337

10/15/24
52° NE



Inspection Photos
Location Name: Simmons A1
Location ID: 326337

10/15/24
72° E



Photo 4. View of one of several Musk Thistle patches observed along the access road.

Inspection Photos
Location Name: Simmons A1
Location ID: 326337

10/15/24
150° SE



Photo 5. View of irrigated grass field reference area.