

# Inspection Photos

October 15th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325160

Inspection Document #: 714001354

La Plata County, CO

Township: NESW 12 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ignacio 33-8 1  
Location ID: 325160

10/15/24  
224° SW



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-05479



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Ignacio 33-8 1  
Location ID: 325160

10/15/24  
86° E



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the southern interim reclamation area that's predominantly Rubber Rabbitbrush.

API #: 067-05479



Inspection Photos  
Location Name: Ignacio 33-8 1  
Location ID: 325160

10/15/24  
78° E



**Photo 3.** Rutting occurring on the active pad.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-05479



10/15/24  
319° NW



**Photo 4.** Prairie dog colony reference area with minimal vegetation.

