

# Inspection Photos

October 15th, 2024

Operator: Arkoma Operations - 10766

Location ID: 311899

Inspection Document #: 714001359

La Plata County, CO

Township: SENW 18 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ige  
Location ID: 311899

10/15/24  
179° S



**Photo 1.** View of the multi well pad taken from the access point facing center.

Inspection Photos  
Location Name: Ige  
Location ID: 311899

10/15/24  
359° N



**Photo 2.** View of eastern fill slope/interim reclamation area dominated by Kochia/Russian Thistle debris.

Inspection Photos  
Location Name: Ige  
Location ID: 311899

10/15/24  
93° E



**Photo 3.** Reference area composed of Sagebrush and James Galleta.