

OFFSET WELL  
EVALUATIONS

| No. | Meet<br>STD | Offset Well<br>API # | Well Name          | Shortest<br>Horizontal<br>Distance<br>From Offset<br>Well to any<br>Proposed HZ<br>Well | Offset Well<br>Operator | Spud Date  | Offset Well<br>Status | Setting<br>Depth | Depth of<br>Deepest<br>Water Well<br>or Base of<br>Fox Hills<br>(DJ) | Productive<br>Casing<br>Cement Top | Most Recent<br>Surface<br>Casing<br>Pressure<br>Reported |
|-----|-------------|----------------------|--------------------|---|-------------------------|------------|-----------------------|------------------|--|------------------------------------|--|
| 1   |             | 05-067-09818         | Ute Southern 704   | 214   | HEC                     |            | AL                    | 0                | 300  | 0                                  |  |
| 2   |             | 05-067-06900         | Southern Ute 15 16 | 317   | Red Willow              | 12/31/1986 | PA                    | 330              | 300  | 5260                               |  |
| 3   |             | 05-067-08078         | Southern Ute 6E    | 366   | Red Willow              | 01/22/1997 | SI                    | 276              | 300  | 1590                               |  |
| 4   |             | 05-067-05077         | Southern Ute 6     | 540   | Red Willow              | 09/19/1961 | SI                    | 215              | 300  | 0                                  |  |
| 5   |             | 05-067-08940         | Southern Ute 704   | 399   | HEC                     |            | AL                    | 0                |  | 0                                  |  |

Total Wells: 5

Meets Standard(STD): 0

Needs Evaluation: 5