

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GGU VAN ORDSTRAND-66S91W/30NESW

Location ID: 335467

Date: 10/17/2024



Location Entrance – Photo #04247



Wellheads – Photo #04251

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GGU VAN ORDSTRAND-66S91W/30NESW

Location ID: 335467

Date: 10/17/2024



Separators – Photo #04248



Tank Battery – Photo #04257