

# Final Reclamation and Stormwater Inspection

Date: 10/16/24

Operator: Crestone Peak Resources Operating LLC -  
10633

Location ID: 455750

Inspection Document #: 713901101

Adams County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Left Hand 3-65 13-18  
Location ID: 455750



**Photo 1.** The photo was taken at the well location facing East. The photo illustrates the Operator location sign and entrance gate.

**Photo 2.** The photo was taken at the well location facing East. The photo illustrates the gravel pad of the plugged location and entry road bollards.

## Inspection Photos

Location Name: Left Hand 3-65 13-18

Location ID: 455750



**Photo 3.** The photo was taken at the well location facing Southwest. The photo illustrates equipment remains at the location.

**Photo 4.** The photo was taken at the well location facing East. The photo illustrates the boundary of the location pad and interim areas.

## Inspection Photos

Location Name: Left Hand 3-65 13-18

Location ID: 455750



**Photo 5.** The photo was taken at the well location facing East. The photo illustrates a small topsoil stockpile within the South interim area.



**Photo 6.** The photo was taken at the well location facing Southeast. The photo illustrates there is a large population of common mullein and scotch thistle growing just beyond the southern boundary of the well location.

## Inspection Photos

Location Name: Left Hand 3-65 13-18

Location ID: 455750



**Photo 7.** The photo was taken at the well location facing North. The photo illustrates a sediment trap in the Northeast corner of the well location.

**Photo 8.** The photo was taken at the well location facing North. The photo illustrates the East side of the location and the main topsoil stockpile.

Inspection Photos

Location Name: Left Hand 3-65 13-18

Location ID: 455750



ECMC  
206° SW  
10/16/24, 1:23 PM

**Photo 9.** The photo was taken at the well location facing Southwest. The photo illustrates the plugged and abandoned well.