

Final Reclamation and Stormwater Inspection

Date: 10/16/24

Operator: Axis Exploration LLc - 10646

Location ID: 460829

Inspection Document #: 713901107

Adams County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Qualls 5-13
Location ID: 460829



Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates the tank battery pad still remains.

Photo 2. The photo was taken at the tank battery location facing South. Refer to the comment for photo 1.



Inspection Photos
Location Name: Qualls 5-13
Location ID: 460829



Photo 3. The photo was taken at the tank battery location facing Northwest. The photo illustrates debris on the pad.



Photo 4. The photo was taken at the tank battery location facing East. The photo illustrates weeds and poor crop growth along the well access road.